

# SOLIDWORKS WORLD 2014



3DEXPERIENCE

## The Big GD&T Theory

Thomas Allsup  
Managing Partner Anida Technologies

# Author: Thomas Allsup

- Thomas received his BSME from Oklahoma State University - Go Pokes!
- In 1990, Thomas got his MSME from University of Texas at Arlington.
- Thomas ended his PhD in Mechanical Engineering from UTA as an All-But-Dissertation in 1994.
- Thomas ended his PhD in General Engineering online from Kennedy Western University.
- Thomas has spent 27 years as a design engineer in consumer products, semiconductor devices, and burn-in sockets.
- [tallsup@anidatech.com](mailto:tallsup@anidatech.com)    [www.anidatech.com](http://www.anidatech.com)    twitter: @anidatech.com

# Dedication

This presentation is dedicated to  
non-PhD mechanical engineer  
Howard Wolowitz and all the other  
Howard Wolowitz's out there!




# Previously at SolidWorks World

2009 : How to Spell GD&T

Introduced the learning  
organizing concept FOPRL:

- Form
- Orientation
- Profile
- Runout
- Location



# Previously at SolidWorks World

2010: The Revenge of the  
Circled Letters

*Remember  
FTPUSMLI?  
Just Kidding*

SolidWorks  
WORLD 2010 | List of Modifiers


- Extent:
  - Free State
  - Tangent Plane
  - Projected Tolerance
  - Unequally Disposed Profile (new)
- Size:
  - Regardless of Feature Size (RFS)
  - Maximum Material Condition (MMC)
  - Least Material Condition (LMC)
  - Independency (new)


F T P U S M L I

# Previously at SolidWorks World

2013: Hitchhiker's Guide to GD&T

Tolerance Zones and Shapes





# Agenda

## Theoretically Speaking

- This hour we will spend some time, not in the twilight zone, but in an equally never-never land known as:


– *PERFECT*

- Datums
- Basic Dimensions



# SolidWorks


*I don't love the description "Reference Geometry" but the concept of datums does't bother SolidWorks users.*



# The Standard



*Datums are so important they are one whole chapter and are on the cover of the previous revision of the standard.*




# Datums

- Datums do one simple thing:
  - ***Datums are a way for the part designer to tell the part inspector how to hold and immobilize the part during inspection.***
- Datums are a reference for geometric dimensions.

# Datum Feature Callout

- Notice that datums now use a “sucker” to attach the datum.
- The sucker can be directly on a surface or on the leader line.
- If the datum is on the leader line and inline with the dimension then the datum is for the center plane.
  - *Feature of size anyone?*
- If the datum is on the leader line and not in line with the dimension then the datum is for the surface.



# Individual versus Related Features


- If an Individual feature is a single surface, element, or size feature then no datum is proper or used.
- Related features must use at least one datum.

# Datum Indicators

- Datum indicators with the “suction” cup can indicate a feature of size simply by placing it in line with the leader line.
- Datum indicators indicate features other than features of size by not aligning the datum line with the leader line.


# What Does it Mean #1?

- This datum is the bottom surface.
- This datum is not a feature of size.
- The datum simulator can be a gauge plate.
  - Gauge plate needs to be 10X flatter than what you want to check.



# What Does It Mean #2?


- This datum is the center axis.
- This datum is a feature of size.
- The datum simulator is a two piece “clamp”.
  - RFS - clamp squeezes
  - MMC - clamp is fixed size





# Example


We'll go control by control through this example later this hour.



# RFS

- A datum that is designated regardless of the feature size can mean a couple of things.
- If the datum isn't a feature of size or simply a surface then it means you lay the datum on a surface plate.
- If the datum is a feature of size then it means that you have to use a “collet” or adjustable surfaces to go make contact with the feature.

# Regardless of Feature Size

- This is the default if no modifier is given.
- The tolerance zone is not affected by the actual size of the feature.
- You don't see the symbol  anymore except in GD&T training sessions.
- Just because you don't see the symbol doesn't mean the concept isn't used all the time.



# Maximum Material Condition

- If a datum has the maximum material modifier then that means you use a fixed size gage that is sized to the maximum material size.
- For external dimensions, use the largest dimension.
  - Thickest plate.
- For internal dimensions, use the smallest value.
  - Smallest hole.
- The actual parts move around in the MMC datum simulator.

# Least Material Condition


- This one is harder to explain since the datum simulator is “virtual”.
- The actual part can not placed in an actual LMC datum simulator.
- We'll calculate the Virtual Condition (VC) of modified features later...

# Fixed Versus Floating

- If you use a datum as “regardless of feature size” then the datum simulator must come in contact with the edge(s).
- If you use a datum as “MMC” or “LMC” then the datum simulator is fixed size and the part moves around inside it.
  - We use a different name for this: gaging.

# Gaging for $.625'' \pm .375''$

- If the material is less than  $1''$  then it can **“GO”**
- If the material is less than  $1/4''$  then it can **“NO GO”**



# Reference to Gaging

- Section 1.1.6 Reference to Gaging “This document is not intended to be a gaging standard.”
- Like so many concepts of GD&T, it is hard to discuss datums without mentioning gaging.
- **Jedi Mind Trick:**
  - **“This is not the gaging standard you are looking for.”**



# Rule of Ten


- If you want to measure a feature accurately, you need a tool that is capable of measuring 1/10 the smallest dimension or tolerance.
- Example: To measure a +/- .001" tolerance you need to .0001" resolution caliper.
- The same thing goes for datums and granite slabs.

# Granite Slabs

Granite materials are black, grey, and crystal pink, each offered in three grades:

- AA-Laboratory for precision operation in constant temperature gaging rooms and metrology departments - 25 millionths
- A-Inspection Grade for general quality control applications - 50 millionths
- B-Toolroom for general production checking work throughout the shop - 100 millionths

# Feature Control Frames




# Points of Contact

- A primary datum feature usually has three points of contact
  - Don't use the word *must*.
- A secondary datum feature usually has two points of contact
  - Don't use the word *must*.
- A tertiary datum feature usually has one point of contact
  - Don't use the word *must*.
- The largest surface on a part doesn't always have to be the primary datum feature.
  - The designer dictates primary datum feature.
  - Usually it is a good design idea for the largest surface to be the primary datum feature.


# Tangent Plane

- This modifier does just like it sounds, it tells the inspector to place a tangent plane on a surface and measure the gauge plate, not the part.
- This modifier is commonly used by orientation controls and sometimes datums.



# Screw Threads, Gears, & Splines

- If a screw thread is called out as a datum then the datum is determined based on the pitch diameter.
- If a gear or spline is called out as a datum then the datum feature must be designated (major, minor, pitch, etc.)




# Simultaneous Requirements

- When you look at a drawing and see the same datums, in the same order, with the same modifiers then all the geometric tolerances are measured at one time – they are simultaneous requirements unless you place the words “SEP REQ” under the tolerance.
  - “Same set up”
- When you see the FRTZF and PLTZF show, we get to discuss the addition of “SIM REQ”.

# Datum Targets

Placing a bold “X” on a point, line, or axis creates a Datum Target with a callout that may or may not include the size of the datum simulator.

- Three points make a datum plane.
- Point and line make a datum plane.
- Two points make a datum axis.





# Datum Definitions

- A Datum is a theoretically exact
  - point
  - axis
  - plane
  - derived from the true geometric counterpart of a specified datum feature.
- A datum is the origin from which the location or geometric characteristics of features of a part are established.

# Datum Definitions

- Datum Feature: an actual feature of a part that is used to establish a datum.
- Datum Feature Simulator: A surface of adequately precise form (such as a surface plate, a gage surface, or a mandrel) contacting the datum feature(s) and used to establish the simulated datum(s).
  - NOTE: Simulated datum features are used as the practical embodiment of the datums during manufacture and inspection.
- Simulated Datum: A point, axis, or plane established by processing or inspection equipment, such as the following simulators: a surface plate, a gage surface, or a mandrel.
- Datum Target: A specified point, line, or area on a part used to establish a datum.

# Datum Reference Frame

- Datum Reference Frame:  
Datums that exist within a framework of three mutually perpendicular intersecting planes.
- Framework datums called:  
Primary - secondary - tertiary



# Feature Control Frames

- Vertical lines between datums in a feature control frame separate primary – secondary – and tertiary datums.
- Horizontal lines between datums in a feature control frame indicate compound datums.
- Datums are never listed purely based on alphabetical order in feature control frames – they might appear in alphabetical order but they are always **“in the desired order of precedence, from left to right.”**

# Clarification of Feature Control Frame

- Draw vertical lines between separate datums:
  - *“Where more than one datum is required, the datum reference letters (each followed by a material condition symbol where applicable) are entered in separate compartments in the desired order of precedence, from left to right.”*
- Draw a horizontal dash between datums to indicate a compound datum.
  - *Pre-ASME Y14.5-1994, the dashes could have meant a datum callout.*

# Missing in Action

- The standard only calls out three letters that cannot be used as datums.
  - I, O, or Q
- The standard does not say you have to start with A and go in any particular order.
  - I prefer to never use S or Z

# Opinion #1

Can you have datums on a drawing without any other GD&T symbols?

Answer #1: No - Without feature control frames, datums are extraneous information so you should not have them alone on a print.

Answer #2: Yes - Unreferenced datums could be considered “reference dimensions” so they could appear alone on a print.

Answer #3: Yes - Notes can use datum callouts so datums could still appear on the face of the drawing and their only reference is in the text notes.

**Common sense says do not use datums without GD&T.**


# Axis of Measurement

- Circularity and cylindricity tolerances do not use datums because they use the features own axis for measurement.
- Circular runout and total runout tolerances use datums as their axis for measurement.



# Updated FOPRL Chart

Now based on ASME Y14.5-2009



|                                    |  |   |                                       |                                     |
|------------------------------------|--|---|---------------------------------------|-------------------------------------|
| <br><b>STRAIGHTNESS</b><br>= 5.4.1 | <br><b>PARALLELISM</b><br>= 6.3.2      | <br><b>LINE PROFILE</b><br>≈ 8.2.1.2    | <br><b>CIRCULAR RUNOUT</b><br>Ⓞ 9.4.1 | <br><b>POSITION</b><br>= 7.2        |
| <br><b>FLATNESS</b><br>= 5.4.2     | <br><b>ANGULARITY</b><br>= 6.3.1       | <br><b>SURFACE PROFILE</b><br>≈ 8.2.1.1 | <br><b>TOTAL RUNOUT</b><br>Ⓞ 9.4.2    | <br><b>SYMMETRY</b><br>= 7.7        |
| <br><b>CIRCULARITY</b><br>Ⓞ 5.4.3  | <br><b>PERPENDICULARITY</b><br>= 6.3.3 |   |                                       | <br><b>CONCENTRICITY</b><br>Ⓞ 7.6.4 |
| <br><b>CYLINDRICITY</b><br>= 5.4.4 |  |   |                                       |                                     |

# Basic Dimensions

- If you think of datums as a method of immobilizing a part then basic dimensions are just offsets from that reference frame.
- Basic dimensions are boxed dimensions.
- Basic dimensions don't have tolerances, they are used by other geometric dimensions.

# Basic Dimensions as Offsets

- Our electrical engineering colleagues use a lot of precise equipment that have a small knob to adjust and output up and down.
- This small difference in the setting and the output is known as an “offset”.
- Mechanically speaking, basic dimensions are offsets from the datum target.

# Basic Dimensions

- Metric Number of Places: Follow same rules as all other dimensions
- English Number of Places: Associated tolerances contain the number of decimal places for control



.500

**.500**

## Opinion #2


- Can you have basic dims without other GD&T symbols?
- Answer #1 - No for English drawings - the number of places in a basic dimension is controlled by its feature control frame that uses it.
- Answer #2 - Yes - Tolerances are indirectly applied to basic dimensions so without a feature control frame that makes a basic dimension a reference dimension.

**Common sense says do not use basic dimensions without GD&T.**


# Orientation Controls

- All three orientation controls requires a datum.
- All orientation controls use basic dimensions:
  - Parallelism has an implied 0 degree basic dimension.
  - Angularity requires an explicit basic angle dimension.
    - *The Basic Dimension value is a angular dimension*
    - *The Feature Control value is linear!!!*
  - Perpendicularity has an implied 90 degree basic dimension.

# Angularity Basic Dimensions




# Position Basic Dimensions






# Profile Basic Dimensions



3DS.COM © Dassault Systèmes

# Ordinate Dimensions?


- Ordinate dimensions are the antithesis of functional dimensioning.
- Functional dimensioning is the heart of GD&T.
- What do I do if my machine shop prefers ordinate dimensions?



# Ordinate Notes

- If you have to use ordinate dimensions, then add two notes like:
  - “All untoleranced dimensions are basic.”
  - “All untoleranced holes are located within XXX of true position.”
- You can now skip the note “NONACCUMULATIVE”.

# Example



# Datum Review

- A Datum is a theoretically exact
  - point
  - axis
  - plane
  - derived from the true geometric counterpart of a specified datum feature.
- A datum is the origin from which the location or geometric characteristics of features of a part are established.

# Basic Dimensions Review

- Basic dimensions are used to orient or locate features with respect to datums.
- Basic dimensions are theoretically perfect and have no tolerance on their own.

# Questions?

- GD&T?
- Datums?
- Basic Dimensions?

# Presentation Available Now

Download This Week After SWW2014

- You can find this and other GD&T and technical PowerPoint presentations on our website.

[www.anidatech.com](http://www.anidatech.com)

- Proceedings with audio will be available in a month or so from SolidWorks.

